Inspection Report

Permit Holder: Aduro Resources Ltd.
Inspection: 2026-3836
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Signage no concerns.

SCV' no venting observed.

Site not in operation.

Both wellheads chained and locked in the closed position, well 12-35 is also isolated.

No other concerns observed at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100045947
Well ID: 18401
Well Name: ADU MONIAS 12-35-082-23
Location: DLS: 12-35-082-23

Permit: 100058496
Well ID: 22502
Well Name: ADU MONIAS A12-35-082-23
Location: DLS: A12-35-082-23

Permit: 100045947
Facility ID: 00020857
Facility Name: ADU MONIAS 12-35-082-23 001
Facility Type: Well Facility
Location: DLS: 12-35-082-23

_____

Authorized by BCER