Inspection Report

Permit Holder: Aduro Resources Ltd.
Inspection: 2026-3844
Inspection Date: 2026-11-23
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Signage no concerns.

Wellhead is isolated and chained in the locked position.

SCV is passing gas (see Non Compliance).

No other concerns identified at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100026873
Well ID: 12913
Well Name: ADU MONIAS 06-35-082-23
Location: DLS: 06-35-082-23

_____

Authorized by BCER