

Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC
Discovery Date: 2026-04-30
As a result of Inspection 2026-1387

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0274-01</p> <p>Issued Date: '2026-05-05'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-06-04'</p>	<p>Permit: 100105388 Well ID: 37099 Well Name: OVV HZ TOWERLAKE A01-10-081-17 Location: DLS: A01-10-081-17</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: 01-10 stain below choke</p> <p>A01-10 packing and stain</p> <p>C01-10 packing and stain</p> <p>E01-10 choke looks clean - stain present</p> <p>F01-10 packing and stain</p>	

Authorized by BCER