

Non-Compliance Notice - Issued

Permit Holder: NTE Energy Canada Ltd.
Discovery Date: 2026-05-05
As a result of Inspection 2026-1399

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0276-01</p> <p>Issued Date: '2026-05-05'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-05-19'</p>	<p>Permit: 100037326 Well ID: 16127 Well Name: NTE CANADA HZ GUNNELL D-A023-J/094-I-13 Location: NTS: D-A023-J/094-I-13</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: LEL gas measured (Altair-5x) at plunger connection of wellhead: audible leak noted.</p>	

<p>Non-Compliance Number: 2026-0276-02</p> <p>Issued Date: '2026-05-05'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p>	<p>Permit: 100037325 Facility ID: 00020179 Facility Name: NTE CANADA GUNNELLCREEK D-023-J/094-I-13 001 Facility Type: Well Facility Location: NTS: D- 023-J/094-I-13</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
---	---

<p>Correction Due Date: '2026-05-19'</p>	
<p>Non-Compliance Comment: Drain plug is missing on the metal storage containment housing two single wall tanks of which one single tank is filled with methanol.</p>	

Authorized by BCER