

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-05-05
As a result of Inspection 2026-1411

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0283-01</p> <p>Issued Date: '2026-05-06'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-06-05'</p>	<p>Permit: 100016657 Well ID: 09074 Well Name: CNRL MARTIN C- 033-E/094-H-06 Location: NTS: C- 033-E/094-H-06</p> <p>Legislation: Drilling and Production Regulation - 25 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well; (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.</p>
<p>Non-Compliance Comment: Suspended well valve handles not chained, locked & secure. No Positive isolation between wellhead and flowline (See attached)</p>	

Authorized by BCER