

Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC
Discovery Date: 2026-05-08
As a result of Inspection 2026-1526

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0302-01</p> <p>Issued Date: '2026-05-13'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-05-27'</p>	<p>Permit: 100082063 Well ID: 31214 Well Name: OVV CRP HZ SUNRISE F04-23-080-17 Location: DLS: F04-23-080-17</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;</p>
<p>Non-Compliance Comment: C needle valve on ESD photos</p> <p>G & M Choke photos</p> <p>F leak wing photo</p>	

Authorized by BCER