

## Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC  
Discovery Date: 2026-05-08  
As a result of Inspection 2026-1527

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0303-01</b></p> <p>Issued Date: <b>'2026-05-13'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-05-27'</b></p>	<p>Permit: 100080845 Well ID: 30508 Well Name: OVV HZ SUNRISE D04-14-080-17 Location: DLS: D04-14-080-17</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;</p>
<p>Non-Compliance Comment: D03-14 - leak stain</p> <p>Note: C3-14, b3-14, H04-14, A04-14, F04-14 - various drips and staining</p>	

---

Authorized by BCER