

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-05-12
As a result of Inspection 2026-1535

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0304-01</p> <p>Issued Date: '2026-05-13'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-06-12'</p>	<p>Permit: 100006253 Well ID: 04407 Well Name: CNRL ET AL W STODDART 08-13-086-21 Location: DLS: 08-13-086-21</p> <p>Legislation: Drilling and Production Regulation 15 (1) Until the well is abandoned, a well permit holder must ensure that a permanently legible and conspicuous sign is displayed and maintained at each well, and that sign must show all of the following: (d) if the well may produce flammable gas, a flammable gas symbol from Schedule 1;</p>
<p>Non-Compliance Comment: Flammable warning decal missing from signage (See attached).</p>	

<p>Non-Compliance Number: 2026-0304-02</p> <p>Issued Date: '2026-05-13'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date:</p>	<p>Permit: 100006253 Well ID: 04407 Well Name: CNRL ET AL W STODDART 08-13-086-21 Location: DLS: 08-13-086-21</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
---	--

'2026-05-27'	
Non-Compliance Comment: Plug missing from needle valve (see attached).	

Authorized by BCER