

## Non-Compliance Notice - Issued

Permit Holder: Shell Canada Limited  
Discovery Date: 2026-05-14  
As a result of Inspection 2026-1604

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p><b>Non-Compliance Number:</b> <b>2026-0311-01</b></p> <p><b>Issued Date:</b> <b>'2026-05-19'</b></p> <p><b>Status:</b> <b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b> <b>14 Days</b></p> <p><b>Correction Due Date:</b> <b>'2026-06-02'</b></p>	<p>Permit: 100074172 Well ID: 27455 Well Name: SHELL HZ GROUND BIRCH 05-05-080-21 Location: DLS: 05-05-080-21</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p><b>Non-Compliance Comment:</b> Plug missing on lower valve assembly.</p>	

---

Authorized by BCER