

Non-Compliance Notice - Issued

Permit Holder: Strathcona Resources Ltd.
Discovery Date: 2026-05-21
As a result of Inspection 2026-1682

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0315-01</p> <p>Issued Date: '2026-05-25'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-08'</p>	<p>Permit: 100017378 Well ID: 09327 Well Name: STRATHCONA RIGEL 10-27-088-18 Location: DLS: 10-27-088-18</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: Plugs missing from valves on pipe coming from ground (See attached). Valves appear to be in open position.</p>	

<p>Non-Compliance Number: 2026-0315-02</p> <p>Issued Date: '2026-05-25'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p>	<p>Permit: 100017378 Well ID: 09327 Well Name: STRATHCONA RIGEL 10-27-088-18 Location: DLS: 10-27-088-18</p> <p>Legislation: Drilling and Production Regulation - 15 15 (3) A well permit holder must ensure both of the following: (a) that the well site is maintained in a condition so as to minimize hazards, including but not limited to hazards associated with pits, holes, storage of materials and equipment; (b) that the well site is free of garbage, debris and derelict equipment.</p>
---	--

<p>Correction Due Date: '2026-06-24'</p>	
<p>Non-Compliance Comment: Various debris, concrete blocks, wood and garbage around site (see attached).</p> <p>Pit has formed around abandoned wellhead site (See attached).</p>	

Authorized by BCER