

Non-Compliance Notice - Issued

Permit Holder: Pavilion Energy Corp.
Discovery Date: 2026-05-27
As a result of Inspection 2026-1737

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0323-01</p> <p>Issued Date: '2026-06-01'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-07-01'</p>	<p>Permit: 100008509 Well ID: 05843 Well Name: PAVILION S STODDART 16-24-085-20 Location: DLS: 16-24-085-20</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: Greasy fluid on various connections, down wellhead, and fluid accumulation at base of wellhead (See attached).</p>	

Authorized by BCER