

## Non-Compliance Notice - Issued

Permit Holder: Bench Creek Resources Ltd.  
Discovery Date: 2026-05-28  
As a result of Inspection 2026-1763

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

|   |  |
|---|--|
| <p>Non-Compliance Number:<br/><b>2026-0329-01</b></p> <p>Issued Date:<br/><b>'2026-06-02'</b></p> <p>Status:<br/><b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration:<br/><b>14 Days</b></p> <p>Correction Due Date:<br/><b>'2026-06-16'</b></p> | <p>Permit: 100039164<br/>Facility ID: 00020463<br/>Facility Name: BENCH CREEK RES MAXHAMISHLAKE C-038-B/094-O-14 002<br/>Facility Type: Well Facility<br/>Location: NTS: C- 038-B/094-O-14</p> <p>Legislation:<br/>Energy Resource Activities Act<br/>37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following:<br/>(a) remedy the cause or source of the spillage;</p> |
| <p>Non-Compliance Comment:</p> <p>LEL detected in meter cabinet for c-A38-B.</p>  |  |

---

Authorized by BCER