

## Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited  
 Discovery Date: 2026-06-02  
 As a result of Inspection 2026-1813

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0340-01</b></p> <p>Issued Date: <b>'2026-06-03'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-06-17'</b></p>	<p>Permit: 100014019          Well ID: 08044          Well Name: CNRL OSPREY B- 015-J/094-A-15          Location: NTS: B- 015-J/094-A-15</p> <p>Legislation:          Energy Resource Activities Act          37 (1) A permit holder and a person carrying out an energy resource activity must          (a) prevent spillage, and</p>
<p>Non-Compliance Comment: Plug missing on needle valve on wellhead (See attached).</p>	

<p>Non-Compliance Number: <b>2026-0340-02</b></p> <p>Issued Date: <b>'2026-06-03'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>30 Days</b></p> <p>Correction Due Date:</p>	<p>Permit: 100014019          Well ID: 08044          Well Name: CNRL OSPREY B- 015-J/094-A-15          Location: NTS: B- 015-J/094-A-15</p> <p>Legislation:          Drilling and Production Regulation          25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following:          (a) suspend the well in a manner that ensures the ongoing integrity of the well;</p>
---	---

'2026-07-03'	
Non-Compliance Comment: Valve handles not chained & locked or removed (See attached).	

---

Authorized by BCER