

Non-Compliance Notice - Issued

Permit Holder: Shell Canada Limited
Discovery Date: 2026-06-11
As a result of Inspection 2026-1973

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0372-01</p> <p>Issued Date: '2026-06-12'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-26'</p>	<p>Permit: 100074195 Well ID: 27548 Well Name: SHELL HZ SUNSET C07-09-080-18 Location: DLS: C07-09-080-18</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (c) remediate any land or body of water affected by the spillage;</p>
<p>Non-Compliance Comment: Staining around wellhead.</p>	

<p>Non-Compliance Number: 2026-0372-02</p> <p>Issued Date: '2026-06-12'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date:</p>	<p>Permit: 100074196 Well ID: 27549 Well Name: SHELL HZ SUNSET D07-09-080-18 Location: DLS: D07-09-080-18</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (c) remediate any land or body of water affected by the spillage;</p>
---	---

'2026-06-26'	
Non-Compliance Comment: Staining on ground around wellhead.	

<p>Non-Compliance Number: 2026-0372-03</p> <p>Issued Date: '2026-06-12'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-26'</p>	<p>Permit: 100074192 Well ID: 27545 Well Name: SHELL HZ SUNSET 07-09-080-18 Location: DLS: 07-09-080-18</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (c) remediate any land or body of water affected by the spillage;</p>
Non-Compliance Comment: Staining on ground around wellhead.	

<p>Non-Compliance Number: 2026-0372-04</p> <p>Issued Date: '2026-06-12'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-26'</p>	<p>Permit: 100074193 Well ID: 27546 Well Name: SHELL HZ SUNSET A07-09-080-18 Location: DLS: A07-09-080-18</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (c) remediate any land or body of water affected by the spillage;</p>
Non-Compliance Comment: Staining on ground around wellhead.	



Non-Compliance Notice Number: 2026-0372
Issued Date: 2026-06-12

Letter ID: L2602780
Letter Date: 2026-06-12

Authorized by BCER