

## Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited  
Discovery Date: 2026-06-16  
As a result of Inspection 2026-2047

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p><b>Non-Compliance Number:</b> <b>2026-0389-01</b></p> <p><b>Issued Date:</b> <b>'2026-06-19'</b></p> <p><b>Status:</b> <b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b> <b>14 Days</b></p> <p><b>Correction Due Date:</b> <b>'2026-07-03'</b></p>	<p>Permit: 100025981 Well ID: 12712 Well Name: CNRL ET AL HZ HELMET B- 052-F/094-P-15 Location: NTS: B- 052-F/094-P-15</p> <p>Legislation: Drilling and Production Regulation 18 (9) A well permit holder must ensure that a well is configured such that (a) the surface casing annulus can freely vent,</p>
<p><b>Non-Compliance Comment:</b> SCVA pipe with ball valve attachment is not connected to the wellhead casing.</p> <p>An additional note is the upper most well wing valve handle is not chained and locked: CNRL to chain and lock upper well handle.</p>	

---

Authorized by BCER