

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-06-16
As a result of Inspection 2026-2054

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0391-01</p> <p>Issued Date: '2026-06-22'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-07-06'</p>	<p>Permit: 100028893 Pipeline Project ID: 000009386 Segment IDs (Location): 1 (From NTS: A- 017-E/094-P-16 To NTS: D- 011-H/094-P-15)</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: Pipeline: ball valve injection/test port is missing a bull plug (ball valve is found adjacent to pig barrel).</p> <p>Note: Pig barrel plastic catchment/ tub cover is not secured to tub: latch is not anchored in closed position.</p>	

Authorized by BCER