

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-06-16
As a result of Inspection 2026-2064

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0396-01</p> <p>Issued Date: '2026-06-22'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-07-06'</p>	<p>Permit: 100028243 Pipeline Project ID: 000009230 Segment IDs (Location): 1 (From NTS: A- 080-D/094-P-16 To NTS: B- 068-D/094-P-16)</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;</p>
<p>Non-Compliance Comment: Pipeline: Two instances of LEL gas were detected at the upper ball valve injection/test ports (with plugs) on two separate ball valves. Visible bubbling from both ball valves was also observed.</p> <p>Both ball valves were located adjacent to the pig barrel closure.</p>	

Authorized by BCER