

Non-Compliance Notice - Issued

Permit Holder: Bench Creek Resources Ltd.
Discovery Date: 2026-06-18
As a result of Inspection 2026-2083

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0401-01</p> <p>Issued Date: '2026-06-23'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-07-23'</p>	<p>Permit: 100050928 Well ID: 20244 Well Name: BENCH CREEK RES ET AL EKWAN A- 013-E/094-I-10 Location: NTS: A- 013-E/094-I-10</p> <p>Legislation: Drilling and Production Regulation - 25 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well; (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.</p>
<p>Non-Compliance Comment: Last gas production March 2024. Well suspension is required under DPR 25(5). Please ensure positive isolation between the well and flowline, and suspend the wellhead by removing or chaining/locking the wellhead valve handles.</p>	

<p>Non-Compliance Number: 2026-0401-02</p> <p>Issued Date: '2026-06-23'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration:</p>	<p>Permit: 100050928 Facility ID: 00021638 Facility Name: BENCH CREEK RES EKWAN A-013-E/094-I-10 001 Facility Type: Well Facility Location: NTS: A- 013-E/094-I-10</p> <p>Legislation: Energy Resource Activities Act - 37 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage; (b) contain and eliminate the spillage;</p>
---	--

<p>14 Days</p> <p>Correction Due Date: '2026-07-07'</p>	
<p>Non-Compliance Comment: Fluid leak from control valve to floor in well building. See photos in Gallery tab of this non-compliance.</p>	

Authorized by BCER