

## Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.  
Discovery Date: 2026-06-24  
As a result of Inspection 2026-2129

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p><b>Non-Compliance Number:</b> <b>2026-0412-01</b></p> <p><b>Issued Date:</b> <b>'2026-06-26'</b></p> <p><b>Status:</b> <b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b> <b>30 Days</b></p> <p><b>Correction Due Date:</b> <b>'2026-07-26'</b></p>	<p>Permit: 100049573 Well ID: 19928 Well Name: TOURMALINE MARTIN D- 095-D/094-H-06 Location: NTS: D- 095-D/094-H-06</p> <p>Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;</p>
<p><b>Non-Compliance Comment:</b> Valve handle not chained &amp; locked or removed (See attached).</p>	

---

Authorized by BCER