

## Non-Compliance Notice - Issued

Permit Holder: NTE Energy Canada Ltd.  
Discovery Date: 2026-06-26  
As a result of Inspection 2026-2146

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0415-01</b></p> <p>Issued Date: <b>'2026-06-26'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-07-10'</b></p>	<p>Permit: 100034368 Well ID: 15288 Well Name: NTE CANADA HZ ELLEH A- 029-C/094-I-12 Location: NTS: A- 029-C/094-I-12</p> <p>Legislation: Drilling and Production Regulation 18 (9) A well permit holder must ensure that a well is configured such that (a) the surface casing annulus can freely vent,</p>
<p>Non-Compliance Comment: Wellhead SCVA ball valve was found in the closed position: SCVA is not venting freely.</p>	

<p>Non-Compliance Number: <b>2026-0415-02</b></p> <p>Issued Date: <b>'2026-06-26'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p>	<p>Permit: 100038588 Well ID: 16563 Well Name: NTE CANADA HZ ELLEH A-A029-C/094-I-12 Location: NTS: A-A029-C/094-I-12</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
---	--

<b>Correction Due Date:</b> <b>'2026-07-10'</b>	
<b>Non-Compliance Comment:</b> Wellhead: flowline upper injection/test port ball valve is missing a bull plug.	

<b>Non-Compliance Number:</b> <b>2026-0415-03</b>	<b>Permit:</b> 100036055
<b>Issued Date:</b> <b>'2026-06-26'</b>	<b>Pipeline Project ID:</b> 000011411
<b>Status:</b> <b>Issued</b>	<b>Segment IDs (Location):</b> 2 (From NTS: A- 029-C/094-I-12 To NTS: A- 022-D/094-I-12)
<b>Outcome:</b>	<b>Legislation:</b> Pipeline Regulation
<b>Correction Duration:</b> <b>14 Days</b>	3 (1) Subject to subsection (2), a pipeline permit holder must not design, construct, operate or maintain any of the following except in accordance with CSA Z662:
<b>Correction Due Date:</b> <b>'2026-07-10'</b>	(a) the pipeline that is the subject of the permit;
<b>Non-Compliance Comment:</b> Pig barrel safety chain is not attached to PAV.	
Also note that catchment tub cover is not secured to basin: open container.	

---

Authorized by BCER