

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
 Discovery Date: 2026-07-03
 As a result of Inspection 2026-2233

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0432-01</p> <p>Issued Date: '2026-07-06'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-07-20'</p>	<p>Permit: 100078060 Road Number: 02629 Segment IDs (Location): 001 (From NTS: C- 065-H/094-G-02 To NTS: D- 008-H/094-G-02)</p> <p>Legislation: Energy Resource Road Regulation (1) A road permit holder must, for each bridge associated with the energy resource road, place and maintain (a) a reflective marker on each corner of the bridge,</p>
<p>Non-Compliance Comment: A reflective corner marker (1x - righthand) was missing at each of the 2, 4, and 17 km bridge locations.</p>	

Authorized by BCER