

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
 Discovery Date: 2026-07-07
 As a result of Inspection 2026-2278

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0448-01</p> <p>Issued Date: '2026-07-09'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-07-23'</p>	<p>Permit: 100105589 Well ID: 36623 Well Name: CNRL HZ NIG CREEK C- 012-A/094-H-04 Location: NTS: C- 012-A/094-H-04</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: Needle valve missing plug (See attached).</p>	

<p>Non-Compliance Number: 2026-0448-02</p> <p>Issued Date: '2026-07-09'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date:</p>	<p>Permit: 100108168 Facility ID: 00026989 Facility Name: CNRL NIG CREEK C-012-A/094-H-04 001 Facility Type: Well Facility Location: NTS: C- 012-A/094-H-04</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;</p>
---	--

'2026-08-08'	
Non-Compliance Comment: Valve leaking crystalized substance and accumulating on floor (see attached)	

Authorized by BCER