

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-07-07
As a result of Inspection 2026-2288

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0453-01</p> <p>Issued Date: '2026-07-09'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-08-08'</p>	<p>Permit: 100005480 Well ID: 03882 Well Name: CNRL W BUICK A- 067-E/094-A-14 Location: NTS: A- 067-E/094-A-14</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: H2S alarm on personal monitor detected around master valve on wellhead.</p>	

Authorized by BCER