

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-07-09
As a result of Inspection 2026-2377

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0468-01 Issued Date: '2026-07-13' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-07-27'	Permit: 100050797 Pipeline Project ID: 000016211 Segment IDs (Location): 1 (From NTS: B- 071-F/094-H-15 To NTS: D- 080-G/094-H-15) Legislation: Pipeline Regulation 3 (1) Subject to subsection (2), a pipeline permit holder must not design, construct, operate or maintain any of the following except in accordance with CSA Z662: (a) the pipeline that is the subject of the permit;
Non-Compliance Comment: Pig launched closure safety chain is not attached to PAV. Note: also observed an open electrical box (exposed wire connections).	

Non-Compliance Number: 2026-0468-02 Issued Date: '2026-07-13' Status: Issued Outcome: Correction Duration: 30 Days	Permit: 100034757 Well ID: 15171 Well Name: CNRL KAHNTAH D- 080-G/094-H-15 Location: NTS: D- 080-G/094-H-15 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.
---	--

Correction Due Date: '2026-08-12'	
Non-Compliance Comment: All wellhead valve handles are not chained/locked (all present not removed) and flowline is connected to the well (not disconnected / blinded): specifically, no positive isolation of the flowline to the well exists. KERMIT last reported gas production is 2022-07 (> 114 months no gas production).	

Authorized by BCER