

Non-Compliance Notice - Issued

Permit Holder: Kelor Rentals Ltd.
Discovery Date: 2026-07-14
As a result of Inspection 2026-2403

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0473-01 Issued Date: '2026-07-14' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-07-28'	Permit: 100056258 Well ID: 21839 Well Name: KELOR BOUNDARY 10-31-084-14 Location: DLS: 10-31-084-14 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;
Non-Compliance Comment: Spillage looks to be coming from two 400bbl tanks load lines. Estimated amount of spillage by view is approximately 3-8 barrels of oil spread across north side of lease. There is no containment for any of the 6-400bbl tanks	

Authorized by BCER