

Non-Compliance Notice - Issued

Permit Holder: Canlin Energy Corporation
Discovery Date: 2026-07-22
As a result of Inspection 2026-2578

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0495-01 Issued Date: '2026-07-22' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-08-05'	Permit: 100033083 Well ID: 14934 Well Name: CANLIN LAPRISE C- 026-I/094-G-08 Location: NTS: C- 026-I/094-G-08 Legislation: Drilling and Production Regulation 18 (9) A well permit holder must ensure that a well is configured such that (a) the surface casing annulus can freely vent,
Non-Compliance Comment: SCVA ball valve handle was found in the closed position: casing annulus cannot vent freely.	

Authorized by BCER