

Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.
Discovery Date: 2026-07-23
As a result of Inspection 2026-2603

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0505-01 Issued Date: '2026-07-24' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-08-07'	Permit: 100112620 Well ID: 41538 Well Name: TOURMALINE HZ TOWN C-L031-H/094-B-09 Location: NTS: C-L031-H/094-B-09 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;
Non-Compliance Comment: Staining in area around wellhead.	

Non-Compliance Number: 2026-0505-02 Issued Date: '2026-07-24' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date:	Permit: 100112620 Well ID: 41538 Well Name: TOURMALINE HZ TOWN C-L031-H/094-B-09 Location: NTS: C-L031-H/094-B-09 Legislation: Drilling and Production Regulation 41 (4) On discovery of a surface casing vent flow other than one referred to in subsection (3), a well permit holder must (a) test the flow rate and buildup pressure of the surface casing vent flow, and
--	--

'2026-08-23'	
Non-Compliance Comment: Containment shows signs of venting.	

Authorized by BCER