

Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.
Discovery Date: 2026-07-28
As a result of Inspection 2026-2691

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0515-01 Issued Date: '2026-07-29' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-08-12'	Permit: 100105510 Facility ID: 00026717 Facility Name: TOURMALINE TOWN B-024-I/094-B-09 001 Facility Type: Well Facility Location: NTS: B- 024-I/094-B-09 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: Chemical injection system has been leaking causing staining on the ground below the pump.	

Non-Compliance Number: 2026-0515-02 Issued Date: '2026-07-29' Status: Issued Outcome: Correction Duration: 14 Days	Permit: 100105510 Facility ID: 00026717 Facility Name: TOURMALINE TOWN B-024-I/094-B-09 001 Facility Type: Well Facility Location: NTS: B- 024-I/094-B-09 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;
---	--

Correction Due Date: '2026-08-12'	
Non-Compliance Comment: Staining on ground below chemical injection pump.	

Authorized by BCER