

Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.
Discovery Date: 2026-07-23
As a result of Inspection 2026-2709

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0518-01 Issued Date: '2026-07-29' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-08-28'	Permit: 100040412 Well ID: 16844 Well Name: TOURMALINE CONROY B-A044-E/094-H-12 Location: NTS: B-A044-E/094-H-12 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.
Non-Compliance Comment: Wellhead: upper valve handle is not chained and locked as per requirements: all valve handles need to be chained and locked to comply with "Suspended Status" operations. Kermi last reported gas production rate: 2023-04 "Suspended Status" (> 14 months no gas production).	

Authorized by BCER