

Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.
Discovery Date: 2026-07-30
As a result of Inspection 2026-2780

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0529-01 Issued Date: '2026-08-05' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-04'	Permit: 100001514 Well ID: 01156 Well Name: SABA O&G BOUNDARY 08-03-086-14 Location: DLS: 08-03-086-14 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.
Non-Compliance Comment: As per the database, this well last produced in December 2023. The wellhead valves need to be chained and locked and the flowline disconnected from the wellhead.	

Authorized by BCER