

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-08-11
As a result of Inspection 2026-2914

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0548-01 Issued Date: '2026-08-14' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-13'	Permit: 100076345 Well ID: 28458 Well Name: CNRL HZ ALTARES C11-19-083-25 Location: DLS: C11-19-083-25 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: The off wing annulus valve is audibly leaking as the valve sits in water.	

Authorized by BCER