

Non-Compliance Notice - Issued

Permit Holder: Canlin Energy Corporation
Discovery Date: 2026-08-20
As a result of Inspection 2026-2986

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0559-01 Issued Date: '2026-08-21' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-09-04'	Permit: 100038766 Well ID: 16469 Well Name: CANLIN LAPRISE A- 002-E/094-H-05 Location: NTS: A- 002-E/094-H-05 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: LEL gas was measured (Altair-5x) at the well building entrance: source of LEL gas is unknown/not found.	

Authorized by BCER