

Non-Compliance Notice - Issued

Permit Holder: Canlin Energy Corporation
Discovery Date: 2026-08-20
As a result of Inspection 2026-3013

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0564-01 Issued Date: '2026-08-21' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-09-04'	Permit: 100012225 Facility ID: 00019024 Facility Name: CANLIN LAPRISECREEK D-087-E/094-H-05 001 Facility Type: Well Facility Location: NTS: D- 087-E/094-H-05 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;
Non-Compliance Comment: LEL gas was measured (Altair-5x) at door entrance of well building and audible leak was noted: no entry into building was completed; therefore, source of LEL gas is unknown/not found.	

Authorized by BCER