

Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.
Discovery Date: 2026-08-20
As a result of Inspection 2026-3104

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0588-01 Issued Date: '2026-08-26' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-25'	Permit: 100004799 Well ID: 03501 Well Name: SABA O&G LAPRISE D- 022-H/094-G-08 Location: NTS: D- 022-H/094-G-08 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;
Non-Compliance Comment: Wellhead: master (1x) and lower wing valves handles (2x) are not all chained and locked (or removed) (disabled well valve handles are required if well is to be managed/proceed to "Suspended Status"). Also note the flowline is not disconnected or blinded (wellhead is not isolated, only flowline control valves handles are closed). KERMIT last reported gas production date: 2025-03 (>17 months no reported gas production).	

Authorized by BCER