

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-08-26
As a result of Inspection 2026-3150

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0598-01 Issued Date: '2026-08-28' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-09-11'	Permit: 100071506 Well ID: 26422 Well Name: CNRL HZ BIRCH A- 032-J/094-A-13 Location: NTS: A- 032-J/094-A-13 Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and
Non-Compliance Comment: Missing plug on needle Valve (See attached).	

Non-Compliance Number: 2026-0598-02 Issued Date: '2026-08-28' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date:	Permit: 100071506 Well ID: 26422 Well Name: CNRL HZ BIRCH A- 032-J/094-A-13 Location: NTS: A- 032-J/094-A-13 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;
--	--

'2026-09-27'	
Non-Compliance Comment: Filter coming from inhibitor fluid tank appears to be leaking from threaded connection and accumulating onto ground (See attached).	
Non-Compliance Number: 2026-0598-03 Issued Date: '2026-08-28' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-27'	Permit: 100073479 Well ID: 27190 Well Name: CNRL HZ BIRCH D-A022-J/094-A-13 Location: NTS: D-A022-J/094-A-13 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: Hissing and odor coming from propane tank (See attached).	

Authorized by BCER