

Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.
Discovery Date: 2026-09-02
As a result of Inspection 2026-3259

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0611-01 Issued Date: '2026-09-09' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-10-09'	Permit: 100062089 Well ID: 23298 Well Name: SABA O&G ET AL LAPRISE D- 090-E/094-H-05 Location: NTS: D- 090-E/094-H-05 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;
Non-Compliance Comment: Wellhead valve handles (master and wing valves) are not disabled (not chained/locked or removed). In addition, the flowline is not isolated from the wellhead (blinded/disconnected). KERMIT last reported gas production date: 2025-03 (>17 months no reported gas production)	

Authorized by BCER