

Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.
Discovery Date: 2026-09-02
As a result of Inspection 2026-3260

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0612-01 Issued Date: '2026-09-09' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-09-23'	Permit: 100038638 Well ID: 16548 Well Name: SABA O&G LAPRISE A- 010-L/094-H-05 Location: NTS: A- 010-L/094-H-05 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: LEL gas was measured (Altair-5x) in well building; source of LEL gas is not found/unknown.	

Authorized by BCER