

Non-Compliance Notice - Issued

Permit Holder: NTE Energy Canada Ltd.
Discovery Date: 2026-09-08
As a result of Inspection 2026-3319

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0629-01 Issued Date: '2026-09-17' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-10-01'	Permit: 100057272 Well ID: 22323 Well Name: NTE CANADA HZ DILLY C-A024-F/094-P-12 Location: NTS: C-A024-F/094-P-12 Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and
Non-Compliance Comment: Wellhead: flowline ball valve injection port is missing a bull plug. Flowline: ARGUS Pig Valve: ball valve injection port is missing a bull plug. Chemical Storage: secondary containment hosting partially filled single wall tanks (2x) is missing a drain plug (not installed).	

Authorized by BCER