

Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.
Discovery Date: 2026-10-21
As a result of Inspection 2026-3552

Notice Comment:

An extensive walk thru this reworked and decompacted area only found 3 live spruce trees and 3 aspen trees from the planted stock. The area walked found no natural recruitment of native tree species. The area is still very heavy in alfalfa and clover with some associated timothy. The effort is recognized, however, the area will have to be reworked to promote the wildlife habitat that existed prior to the oil and gas activity. It is recognized there will need to be an extension due to lateness in the season and the work to be carried out in 2027.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0682-01 Issued Date: '2026-10-26' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-11-25'	Permit: 100057613 Road Number: 00278 Segment IDs (Location): 016 (From NTS: C- 064-D/094-A-13 To NTS: C- 090-L/094-A-12) Legislation: Environmental Protection and Management Regulation 19 (1) A person who carried out an oil and gas activity on an operating area and who no longer intends to do so must, as soon as practicable, restore the operating area by doing the following: (d) re-vegetating any exposed soil on the operating area using seed or vegetative propagules of an ecologically suitable species that (i) promote the restoration of the wildlife habitat that existed on the area before the oil and gas activity was begun, and
Non-Compliance Comment:	

Authorized by BCER



Non-Compliance Notice Number: 2026-0682
Issued Date: 2026-10-26

Letter ID: L2605100
Letter Date: 2026-10-26