Non-Compliance Notice - Issued

Permit Holder: Strathcona Resources Ltd.
Discovery Date: 2026-11-18
As a result of Inspection2026-3797

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0735-01** Issued Date: **'2026-11-22'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-12-06'**	Permit: 100108292 Road Number: 05364 Segment IDs (Location): 001 (From NTS: D- 032-B/094-H-02 To NTS: D- 035-B/094-H-02) Legislation: Energy Resource Road Regulation (1) A road permit holder must, for each bridge associated with the energy resource road, place and maintain (a) a reflective marker on each comer of the bridge,
Non-Compliance Comment: Reflective markers are missing on each corner of bridge (See attached).	

_____

Authorized by BCER