Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-11-23
As a result of Inspection2026-3825

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0739-01** Issued Date: **'2026-11-24'** Status: **Issued** Outcome: Correction Duration: **30 Days** Correction Due Date: **'2026-12-24'**	Permit: 100000688 Well ID: 00538 Well Name: CNRL W BEATTON D- 038-K/094-H-02 Location: NTS: D- 038-K/094-H-02 Legislation: Energy Resource Activities Act - 37 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage; (b) contain and eliminate the spillage;
Non-Compliance Comment: Needle valve leaking unknown substance from handle onto ground (see attached).	

_____

Authorized by BCER